Operator: LIBERTY ENERGY (MID-STATES) CORP D/B/A LIBERTY UTILITIES - CENTRAL	Operator ID#: 38906
Inspection Date(s): 11/18/2014 (Half), 11/19/2014, 11/20/2014, 11/21/2014	Man Days: 3.5
Inspection Unit: Harrisburg	•
Location of Audit: Harrisburg	
Exit Meeting Contact: David Hinds	
Inspection Type: Standard Inspection - Record Audit	
Pipeline Safety Representative(s): Jim Watts	
Company Representative to Receive Report: David Hinds, Michael Beatty, Ron Snider	
Company Representative's Email Address: david.hinds@libertyutilities.com, mike.beatty@libRonald.Snider@libertyutilities.com	ertyutilities.com,

Headquarters Address Information:	2370 North High Street Suite 1	
	Jackson, MO 63755	
	Emergency Phone#: (855) 644-8134	
	Fax#:	
Official or Mayor's Name:	David Swain	
	Phone#: (573) 755-0107	
	Email: david.swain@libertyutilities.com	
Inspection Contact(s)	Title	Phone No.
David Hinds	Manager Compliance and Measurement	(573) 221-4964
Deon Scott	Manager Operations - Harrisburg - Metropolis	(618) 253-7041
Ron Snyder	Manager Compliance and Measurement	(573) 471-9919

Gas System Operations	Status
Gas Transporter	Texas Eastern
Annual Report (Form 7100.1-1) reviewed for the year:	Satisfactory
Unaccounted for Gas	1.6-1.8%
Number of Services	25,838
General Comment:	·
This is the total service count for Illinois for 2013.	
Miles of Main	695

General Comment:		
These are companywide numbers for Illinois service are	a.	
Is the operator maintaining documentation ve (MAOP)	erifying their Maximum Allowable Operating Pressure(s)?	Satisfactory
General Comment:		
The MAOP records are maintained in Jackson, Missouri that is maintained by engineering.	at Liberty Mid States Headquarters. MAOP's have been determined by	pressure test using prior data
Operating Pressure (Feeder)		397,
Operating Pressure (Town)		20,23.5,30,40,45,50,60,7
Operating Pressure (Other)		Not Applicable
General Comment:		
There are no other operating pressure classifications util	lized in the Liberty Systems.	
MAOP (Feeder)		397,150,80
MAOP (Town)		26,50,60
MAOP (Other)		Not Applicable
General Comment:		I
There are no other types of MAOP's.		
Does the operator have any transmission pip	elines?	No
General Comment:		I
There is no Transmission in the Harrisburg Service area		
Regulatory	Reporting Records	Status
[191.5]	Were Telephonic Notices of Incidents reported to the NRC (800-424-8802)?	Not Applicable
General Comment:	•	
There were no reportable incidents in 2012-2013.		
[191.9(a)]	Was a DOT Incident Report Form F7100.1 submitted within 30 days after detection of an incident?	Not Applicable
General Comment:	<u> </u>	
There were no reportable incidents in 2012-2013.		
[191.9(b)]	Were any supplemental incident reports submitted when deemed necessary?	Not Applicable
General Comment:	·	<u> </u>

Did the operator have any plastic pipe fa	ailures in the past calendar year?	Not Applicable
General Comment:	and the fraction of the fracti	Not Applicable
There were no plastic piping failures that required	reporting in 2012-2013	
Did the operator take action to mitigate s components?	safety concerns relating to the failure of the PE or pipeline	Not Applicable
General Comment:	L	
There have been no plastic piping failures that req	uire mitigation of any safety concerns.	
[191.23(a)]	Did the operator report Safety Related Conditions?	Not Applicable
General Comment:		
There were no safety related conditions that occur	rred in 2012-2013.	
[191.25]	Did the Operator file a Safety Related Condition Report within 5 working days of determination, but not later than 10 working days after discovery?	Not Applicable
General Comment:		
There were no safety related conditions that occur	rred in 2012-2013.	
[192.16(c)]	Customer Notification: Has the operator notified each new customer within 90 days about the customer's responsibility regarding buried piping, however, operators of a master meter may continuously post a general notice in a permanent location?	Satisfactory
	DRUG TESTING	Status
Refer to Drug and Alcohol Inspection Fo	rms and Protocols	Not Checked
General Comment:		
The drug and alcohol records were not reviewed of Missouri Headquarters.	luring this audit. This was reviewed during the DA Plan audit conducted in April o	of 2014 at the Jackson,
TES	ST REQUIREMENTS	Status
[192.517(a)][192.505,192.507,192.511(c	Are pressure test records being maintained for piping operating above 100 psig?	Satisfactory
General Comment:		
Staff reviewed pressure tests for piping operating	above 100 psig for 2012-2013 and were tested at 650 psig.	
	Are pressure test records being maintained for at	Satisfactory
[192.517(b)][192.511,192.509,192.513]	least 5 years on piping operating below 100 psig?	oatistactory

Unless otherwise noted, all code references are to 49CFR Part 192.

If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Staff reviewed pressure test documentation for piping operating below 100 psig installed in 2012-2013 and were tested at 120 psig.

Clair reviewed products tool decarrientation for	piping operating below 100 psig installed in 2012-2013 and were tested at 120 psig	j.
[192.603(b)][192.725]	Were service lines temporarily disconnected from the main properly tested prior to reconnection?	Satisfactory
General Comment:		
Staff reviewed pressure tests for reinstated ser	vices for 2012-2013.	
	UPRATING	Status
Category Comment:		
No uprating was conducted in 2012-2013 in the	e Harrisburg service area.	
[192.555][192.555]	Has the operator maintained documentation of uprating activities when uprating a pipe to a pressure that will produce a hoop stress of 30% or more SMYS?	Not Applicable
[192.557][192.557]	Has the operator maintained documentation of uprating activities when uprating a pipe to a pressure that will produce a hoop stress of less than 30% SMYS?	Not Applicable
	OPERATIONS	Status
[192.603(b)][192.605(a)]	Has the operator conducted a review of the Operations and Maintenance Manual once per yr/15 months?	Satisfactory
General Comment:		
Staff reviewed documentation indicating the O	&M was reviewed as required in 2012-2013.	
Has the operator conducted a review	of the Operator Qualification Plan once per yr/15 months?	Yes
General Comment:	<u> </u>	
The OQ plan was reviewed annually as part of	the O&M in 2012-2013. The review documentation is maintained with the O&M.	
[192.603(b)][192.605(b)(3)]	Are construction records, maps, and operating history available to operating personnel?	Satisfactory
General Comment:		
The maps are available electronically to field po available at the Harrisburg Office.	ersonnel, operating history and construction records are available electronically or to	hrough paper documentation
[192.603(b)][192.605(b)(8)]	Has the operator periodically reviewed personnel's work to determine the effectiveness of normal O&M procedures when deficiencies are found?	Not Applicable
General Comment:	<u> </u>	
completed. The supervisor then reviews the ta the issue is discussed with the employee and to	ocated in the Wennsoft Program that are task specific and require the employee to risks performed to determine they were completed correctly. If tasks were not record he tasks is corrected or if necessary the task is performed again. Compliance persues where procedures were revised due to inspections performed in 2012-2013. Issue	ded being completed correct onnel also conduct reviews

are sent to the Corporate Office for corrective a	actions.	
CONTINUI	NG SURVEILLANCE RECORDS	Status
[192.603(b)][192.613(a)]	Has the operator reviewed continuing surveillance records for class location changes, failures, leak history, corrosion, changes in cathodic protection, and other unusual operating and maintenance conditions?	Satisfactory
General Comment:	<u> </u>	
Staff reviewed patrols, failures, leak history, ch	anges in cathodic protection and other unusual operating and maintenance condition	ons.
There were no changes to class location in 20 Liberty has initiated a replacement program for	12, 2013. Leaks were repaired as required and corrosion issues were corrected when been steel and PVC piping remaining in the Illinois system.	nen deficiencies were observed.
Due to the overpressure of the Muddy System valve sticking on the pilot regulator.	on the 4th of February, 2014, 1805P reliefs were exchanged with 1808 reliefs due	to issues detected to a needle
[192.491][192.489]	Does the operator have records verifying if exposed cast iron was examined for evidence of graphitization and if necessary what appropriate action was taken concerning graphitization?	Not Applicable
General Comment:		
There is no Cast Iron in the Illinois Service Are	a.	
[192.603(b)][192.755]	Does the operator have surveillance records of cast iron pipelines, including appropriate action resulting from tracking circumferential cracking failures, study of leak history, or any other unusual operating and maintenance conditions?	Not Applicable
General Comment:	<u> </u>	
There is no Cast Iron in the Illinois Service Are	a.	
[192.603(b)][192.753(a)]	Is each cast iron caulked bell and spigot joint that is subject to a pressure of more than 25 (psig.) sealed as required?	Not Applicable
General Comment:		
There is no Cast Iron in the Illinois Service Are	a.	
[192.603(b)][192.753(b)]	Is each cast iron caulked bell and spigot joint that is subject to a pressure of 25 (psig.) or less and is exposed for any reason sealed as required?	Not Applicable
General Comment:		
There is no Cast Iron in the Illinois Service Are	a.	
QUALIFICA	TION OF PIPELINE PERSONNEL	Status
Refer to operator Qualification Inspec	tion Forms and Protocols	Not Checked

Unless otherwise noted, all code references are to 49CFR Part 192.

If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

General Comment:

The Operator Qualification plan was not reviewed as part of this inspection. Staff did review the OQ qualifications of the Harrisburg Personnel to ensure that they were current on their qualifications in 2012-2013.

DAMAGE PREVENTION RECORDS

		1
[192.603(b)][191.11(a)]	Did the operator track the number of damages per 1000 locate requests for the previous years?	Satisfactory
General Comment:		
2012 - 8806 locates with 34 damages and 2013	- 7933 locates with 35 damages.	
Has the number of damages increased	or decreased from prior year?	Increased

General Comment:

Due to the increase in the number of damages per 1000 locates, in 2014 Liberty improved the review process for third party damages used to establish the cause for the damage. They reiterated to employees that all services shall be abandoned as close as practical to the main. Stubs cannot be left unless approved by Engineering. Third party damages are now being sent to the finance department to ensure the excavator is being billed for any damages. Liberty is also submitting damage reports to JULIE Enforcement to the ICC for review. Excavator meetings have been held with repeat offenders who are not following one call laws.

Staff reviewed the findings of the reviews conducted and determined that a majority of the damages were due to excavators not following the current damage prevention laws. If an employee is found not following established procedures the employee is disqualified and receives training and is requalified of which has not been the case in Harrisburg service area or in Illinois.

[192.603(b)][192.617]	Does the operator track records of accidents due	
	to excavation damage to ensure causes of failures	Satisfactory
	are addressed to minimize the recurrence?	

General Comment:

In 2014 Liberty established a review process for third party damages to establish the cause for the damage. They reiterated to employees that all services shall be abandoned as close as practical to the main. Stubs cannot be left unless approved by Engineering. Third party damages are now being sent to the finance department to ensure the excavator is being billed for any damages. Liberty is also submitting damage reports to JULIE Enforcement to the ICC for review. Excavator meetings have been held with repeat offenders who are not following one call laws. Staff reviewed the findings of the reviews conducted and determined that a majority of the damages were due to excavators not following the current damage prevention laws. If an employee is found not following established procedures the employee is disqualified and receives training and is requalified of which has not been the case in Harrisburg service area or in Illinois.

[192.603(b)][192.614(c)(3)]	Does the operator provide documentation pertaining to notification of excavation, marking, positive response, and the availability and use of the one call system?	Satisfactory
-----------------------------	--	--------------

General Comment:

Kortera software is utilized to notify the excavator if no Liberty gas facilities are present. All locates are responded to and marked accordingly. The supervisors receive reports indicating when locates are not conducted within the times as required by the one call laws. Staff reviewed reporting utilized by Liberty to determine how many locates were responded to within the required interval reviewed completed random locates to review comments that were recorded by the employee performing the locate. Staff reviewed the listing of locates performed late and found that they were joint meets or the locates on large jobs that had been started but completed after the dig start time.

Does the operator have a Quality Assurance Program in place for monitoring the locating and marking of facilities?	Yes

General Comment:

Liberty does not currently have a QA program in place but monitors the damages to facilities by conducting field reviews of the completed locate request to determine if they were completed and marked correctly.

Status

Do pipeline operators include performand	ce measures in facility locating contracts?	Not Applicable
General Comment:		
liberty does not utilize contract locators. Locates a	are performed by company employees.	
[IL ADM. CO.265.100(b)(1)]	Was third party damage to mains involving a release of gas reported to ICC JULIE Enforcement? http://www.icc.illinois.gov/julie/	Satisfactory
Has the Operator adopted applicable sec	ctions of the Common Ground Alliance Best Practices?	Yes
General Comment:	<u> </u>	
iberty has adopted the applicable best practices for	or damage prevention.	
f no, were Common Ground Alliance Be	st Practices discussed with Operator?	Not Applicable
General Comment:	-	
N/A Liberty has adopted the applicable best practic	ees for damage prevention.	
EN	IERGENCY PLANS	Status
[192.603(b)][192.615(b)(1)]	Are supervisors, responsible for emergency action, furnished copies of the latest edition of the Emergency Plan?	Satisfactory
General Comment:		
Supervisors are provided a copy of the latest editio	n of the emergency plan.	
[192.603(b)][192.615(b)(2)]	Has the operator maintained documentation that the appropriate operating personnel have received training to assure they are knowledgeable of emergency procedures and that the training was effective?	Satisfactory
General Comment:		
Staff reviewed documentation indicating operating	personnel received training on the Emergency Plan in November of 2012 and in	February of 2013.
[192.603(b)][192.615(b)(3)]	Has the operator maintained documentation of employee activity reviews to determine whether the procedures were effectively followed in each emergency?	Satisfactory
General Comment:	· · · · · · · · · · · · · · · · · · ·	
Supervisors conduct reviews are of all of the emerg	gency tickets to determine whether the procedures were effectively followed.	
[192.603(b)][192.615(c)]	Has the operator maintained documentation that the operator established and maintained liaison with appropriate fire, police and other public officials?	Satisfactory

[192.603(b)][192.615(a)(3)]	Did the review of emergency response time	
[1021000(0)][1021010(0)(0)]	intervals regarding odor/leak complaint	Satisfactory
	documentation indicate adequate emergency	Satisfactory
	response intervals were achieved?	
General Comment:		
There were no calls in 2013 that exceeded one h	calls that exceeded one hour in 2013 were due to remote computer issues or failu nour due to weather, multiple leak calls or after hour call outs. Average response to of a natural disaster the call centers are notified that an emergency has occurred to	imes in 2013 were 20 minut
PUBLIC AWA	RENESS PROGRAM - RECORDS	Status
Refer to Public Awareness Program Ins	spection Forms and Protocols	Not Checked
General Comment:		
The Public Awareness plan was not reviewed as	s part of this audit.	
10	DORIZATION OF GAS	Status
[192.603(b)][192.625(f)]	Has the operator maintained documentation of	
	odorant concentration level testing using an	Satisfactory
	in at more and O	
	instrument? e tested annually for their ability to detect odorant. Odorometer tests were conducted to the conduction of	
Employees who perform odorant level testing are monthly basis. Random review of completed tes performed by company personnel when they corthe level of detection.	e tested annually for their ability to detect odorant. Odorometer tests were conducts indicated odorant levels were maintained with detection levels at 0.25 pounds product orders that allow access to natural gas. During this test only a sniff test is permitted. Has the operator maintained documentation of	er mmcf. Sniff checks are
Employees who perform odorant level testing are monthly basis. Random review of completed test performed by company personnel when they conthe level of detection. [192.603(b)][192.625(e)]	e tested annually for their ability to detect odorant. Odorometer tests were conduct sts indicated odorant levels were maintained with detection levels at 0.25 pounds p anduct orders that allow access to natural gas. During this test only a sniff test is pe	er mmcf. Sniff checks are erformed and does not quan
Employees who perform odorant level testing are monthly basis. Random review of completed test performed by company personnel when they conthe level of detection. [192.603(b)][192.625(e)] General Comment:	e tested annually for their ability to detect odorant. Odorometer tests were conducts indicated odorant levels were maintained with detection levels at 0.25 pounds product orders that allow access to natural gas. During this test only a sniff test is per Has the operator maintained documentation of odorizer tank levels?	er mmcf. Sniff checks are erformed and does not quan Satisfactory
Employees who perform odorant level testing are monthly basis. Random review of completed test performed by company personnel when they conthe level of detection. [192.603(b)][192.625(e)] General Comment:	e tested annually for their ability to detect odorant. Odorometer tests were conducts indicated odorant levels were maintained with detection levels at 0.25 pounds product orders that allow access to natural gas. During this test only a sniff test is permitted. Has the operator maintained documentation of	er mmcf. Sniff checks are erformed and does not quan Satisfactory
Employees who perform odorant level testing are monthly basis. Random review of completed test performed by company personnel when they conthe level of detection. [192.603(b)][192.625(e)] General Comment: There is one injection odorizer at the main supply	e tested annually for their ability to detect odorant. Odorometer tests were conducts indicated odorant levels were maintained with detection levels at 0.25 pounds product orders that allow access to natural gas. During this test only a sniff test is per Has the operator maintained documentation of odorizer tank levels?	er mmcf. Sniff checks are erformed and does not quan Satisfactory
Employees who perform odorant level testing are monthly basis. Random review of completed test performed by company personnel when they conthe level of detection. [192.603(b)][192.625(e)] General Comment: There is one injection odorizer at the main supplymonthly tank inspections in 2012-2013.	e tested annually for their ability to detect odorant. Odorometer tests were conducted indicated odorant levels were maintained with detection levels at 0.25 pounds product orders that allow access to natural gas. During this test only a sniff test is permitted. Has the operator maintained documentation of odorizer tank levels? The detection of the detection levels at 0.25 pounds product orders that allow access to natural gas. During this test only a sniff test is permitted to odorizer tank levels? Are master mater operators at the Harco and Storage field the verification of odorant concentration levels from	er mmcf. Sniff checks are efformed and does not quan Satisfactory ake points. They conducted
Employees who perform odorant level testing are monthly basis. Random review of completed test performed by company personnel when they conthe level of detection. [192.603(b)][192.625(e)] General Comment: There is one injection odorizer at the main supplymonthly tank inspections in 2012-2013. [192.603(b)][192.625(f)(1)]	e tested annually for their ability to detect odorant. Odorometer tests were conducts indicated odorant levels were maintained with detection levels at 0.25 pounds product orders that allow access to natural gas. During this test only a sniff test is per Has the operator maintained documentation of odorizer tank levels? If y to the Harrisburg system and a bypass odorizer at the Harco and Storage field tank the master meter operators receiving written verification of odorant concentration levels from their gas supplier?	er mmcf. Sniff checks are efformed and does not quan Satisfactory ake points. They conducted
Employees who perform odorant level testing are monthly basis. Random review of completed test performed by company personnel when they conthe level of detection. [192.603(b)][192.625(e)] General Comment: There is one injection odorizer at the main supplymonthly tank inspections in 2012-2013. [192.603(b)][192.625(f)(1)] General Comment: This does not apply to this operator as they are respectively.	e tested annually for their ability to detect odorant. Odorometer tests were conducted its indicated odorant levels were maintained with detection levels at 0.25 pounds product orders that allow access to natural gas. During this test only a sniff test is permitted. Has the operator maintained documentation of odorizer tank levels? The product orders that allow access to natural gas. During this test only a sniff test is permitted to the product orders that allow access to natural gas. During this test only a sniff test is permitted to the product of th	er mmcf. Sniff checks are efformed and does not quan Satisfactory ake points. They conducted
Employees who perform odorant level testing are monthly basis. Random review of completed test performed by company personnel when they conthe level of detection. [192.603(b)][192.625(e)] General Comment: There is one injection odorizer at the main supplymonthly tank inspections in 2012-2013. [192.603(b)][192.625(f)(1)] General Comment: This does not apply to this operator as they are respectively.	e tested annually for their ability to detect odorant. Odorometer tests were conducts indicated odorant levels were maintained with detection levels at 0.25 pounds product orders that allow access to natural gas. During this test only a sniff test is per Has the operator maintained documentation of odorizer tank levels? If y to the Harrisburg system and a bypass odorizer at the Harco and Storage field tank the master meter operators receiving written verification of odorant concentration levels from their gas supplier?	er mmcf. Sniff checks are efformed and does not quan Satisfactory ake points. They conducted
Employees who perform odorant level testing are monthly basis. Random review of completed test performed by company personnel when they continued the level of detection. [192.603(b)][192.625(e)] General Comment: There is one injection odorizer at the main supplymonthly tank inspections in 2012-2013. [192.603(b)][192.625(f)(1)] General Comment: This does not apply to this operator as they are referenced to the performance of the performance	e tested annually for their ability to detect odorant. Odorometer tests were conducts indicated odorant levels were maintained with detection levels at 0.25 pounds product orders that allow access to natural gas. During this test only a sniff test is periodic orders that allow access to natural gas. During this test only a sniff test is periodic orders that allow access to natural gas. During this test only a sniff test is periodic orders that allow access to natural gas. During this test only a sniff test is periodic at the test only a sniff test is periodic orders. Has the operator maintained documentation of odorant concentration levels from their gas supplier? Has the master meter operator maintained documentation of sniff tests performed as required	Satisfactory Satisfactory Alternative points. They conducted Not Applicable
Employees who perform odorant level testing are monthly basis. Random review of completed test performed by company personnel when they conthe level of detection. [192.603(b)][192.625(e)] General Comment: There is one injection odorizer at the main supplymonthly tank inspections in 2012-2013. [192.603(b)][192.625(f)(1)] General Comment:	e tested annually for their ability to detect odorant. Odorometer tests were conduct its indicated odorant levels were maintained with detection levels at 0.25 pounds product orders that allow access to natural gas. During this test only a sniff test is periodic orders that allow access to natural gas. During this test only a sniff test is periodic orders that allow access to natural gas. During this test only a sniff test is periodic orders that allow access to natural gas. During this test only a sniff test is periodic orders that allow access to natural gas. During this test only a sniff test is periodic orders to not a master meter operator and Storage field that a master meter operator orders are ceiving written verification of odorant concentration levels from their gas supplier? Has the master meter operator maintained documentation of sniff tests performed as required by this section?	Satisfactory Satisfactory Alternative points. They conducted Not Applicable

[192.603(b)][192.721(b)(1)]	Is the operator patrolling business districts at a minimum of 4 per year/4 1/2 months?	Satisfactory
General Comment:		
Patrols on piping located in business districts were cond	lucted on a quarterly basis in 2012-2013.	
[192.603(b)][192.721(b)(2)]	Is the operator patrolling outside business districts at a minimum of 2 per year/7 1/2 months?	Satisfactory
General Comment:	·	
	d on a quarterly basis in 2012-2013. Review of the 2012 -2013 patrols inc ing patrols such as missing markers, exposed pipe or coating and paint is:	
[192.603(b)][192.723(b)(1)]	Is the operator performing leakage surveys in business districts at a minimum of 1 per year/ 15 months? If the operator has inside meter sets that meet this criterion then were those surveyed?	Satisfactory
General Comment:		
Review of the Business District leak surveys in the Harri	sburg service area indicates they were conducted annually in 2012-2013	as required.
[192.603(b)][192.723(b)(2)]	Is the operator performing leakage surveys outside a business district at a minimum of every 5 years/63 months? Is the operator performing leakage surveys on cathodically unprotected pipelines at a minimum of every 3 years/39 months? If the operator has inside meter sets that meet this criterion then were those surveyed? If the operator has yard lines then are those being surveyed?	Satisfactory
General Comment:		
Review of the residential leakage surveys conducted on cycle as required. Bare or poorly coated piping surveys Line surveys due in 2012-2013 were conducted as requi	protected and plastic piping performed in 2012-2013 indicates the survey in residential areas in 2012-2013 were conducted annually as required by ired on a three year interval.	s were completed on a five year company procedure. Yard
YARD LIN	IES - RESIDENTIAL	Status
[220 ILCS 2.2.03]	Has the operator designated and documented the location of all services where the meter is located	
	more than 3 feet away from the wall of a residence?	Satisfactory
General Comment:	more than 3 feet away from the wall of a	Satisfactory
General Comment: Leak surveys for yard lines due in 2012-2013 were comp	more than 3 feet away from the wall of a residence?	Satisfactory
	more than 3 feet away from the wall of a residence?	Satisfactory
Leak surveys for yard lines due in 2012-2013 were comp	more than 3 feet away from the wall of a residence? pleted as required on a three year cycle. Has the operator determined if cathodic protection	

[192.723(b)(1),192.723(b)(2)][220 ILCS 2.2.03]	After the determination of the cathodic protection requirements, has the operator surveyed each line within the required leakage survey intervals?	Satisfactory
General Comment:		
All yard lines are surveyed on a three year cycle.		
ABANDONMENT or DEACTIVAT	TION of FACILITIES PROCEDURES	Status
[192.603(b)][192.727(b)]	Did the operator maintain documentation demonstrating that each pipeline abandoned in place was disconnected from all sources and supplies of gas, and purged of gas?	Satisfactory
General Comment:		
Review of retirement orders for 2012-2013 indicates that aba	ndoned pipelines were disconnected from its source and were purged	d as required.
[192.603(b)][192.727(c)]	Did the operator maintain documentation demonstrating that each inactive pipeline that is not being maintained under this part was disconnected from all sources and supplies of gas; purged of gas?	Satisfactory
General Comment:		
Review of retirement orders for 2012-2013 indicates that aba	ndoned pipelines were disconnected from its source and were purged	d as required.
[192.603(b)][192.727(d)]	Did the operator maintain documentation demonstrating that whenever service to a customer was discontinued access to gas was either; locked, prevented by a mechanical fitting, or disconnected from the gas supply and open pipe ends sealed?	Satisfactory
General Comment:	p.p.c c.i.as session.	
Review of service orders for service disconnects performed in customers piping.	n 2012-2013 indicates the gas supply was secured by locking the valv	ve or disconnecting the
[192.603(b)][192.727(e)]	Did the operator maintain documentation when air was used for purging that a combustible mixture was not present after purging?	Satisfactory
General Comment:	<u> </u>	
Review of retirement orders for 2012-2013 indicates that aba	ndoned pipelines were disconnected from its source and were purged	d as required.
[192.727(g)][192.727(g)]	Did the operator maintain documentation for each abandoned onshore pipeline facility that crosses over, under or through a commercially navigable waterway?	Not Applicable
General Comment:	<u> </u>	
Liberty has no piping that crosses a navigable water way in the	ne Harrisburg Service Area	
Liberty has no piping that crosses a havigable water way in ti	іе патіълиту зетутсе Атеа.	

Imiting and regulating stations at a minimum of 1 Satisfactory per year/15 months?	PRESSURE LIN	MITING AND REGULATION	Status
Review of the 2012-2013 inspections for pressure regulating and overpressure protection equipment in the Harrisburg system indicated the inspections were conducted within the allowable time frames and were set within allowable pressure ranges for the applicable MAOF? In 22,603(b)][192,743(a)] Is the operator inspecting pressure limiting and regulating stations for adequate capacity at a minimum of 1 per year/15 months? Seneral Comment: Review of capacity reviews conducted in 2012-2013 indicate adequate relief capacities are being maintained in the Harrisburg system. If the operator used calculations to determine sufficient capacity, were the calculation reviews documented at a minimum of 1 per year/15 months? Satisfactory months? Satisfactory documente: Review of 2012-2013 capacity reviews conducted by engineering indicate they were reviewed as required and were found to have adequate capacities. Is each distribution system supplied by more than one district pressure regulating station, or where required by the operator on a system supplied by a single regulating station, equipped with telemetering or recording pressure surges to indicate the gas pressure in the district? Seneral Comment: Whill led systems are monitored by pressure recording charts. Staff conducted a random review of pressure recording charts and observed no indications of abnormal pressures in 2012-2013. If there were indications of abnormally high- or low-pressure, were actions taken to correct any unsatisfactory operating conditions? Seneral Comment: Review of random weekly charts for 2012-2013 indicate there were no excessive high or low pressures observed. 192.603(b)][192.743(a),192.743(b),192.195(b)(2)] Is overpressure protection provided by the supplier pipeline downstream of the take point? Seneral Comment: Currently Liberty is in the process of purchasing property at both take points in the Harrisburg system to allow for these stations to be rebuilt and will include beverpressure protection as part of the new design.	[192.603(b)][192.739(a)]	limiting and regulating stations at a minimum of 1	Satisfactory
Is the operator inspecting pressure limiting and regulating stations for adequate capacity at a minimum of 1 per year/15 months? Satisfactory minimum of 1 per year/15 months?	General Comment:		
regulating stations for adequate capacity at a minimum of 1 per year/15 months? Seneral Comment: Review of capacity reviews conducted in 2012-2013 indicate adequate relief capacities are being maintained in the Harrisburg system. 192.603(b)][192.743(b)] If the operator used calculations to determine sufficient capacity, were the calculation reviews documented at a minimum of 1 per year/15 months? Satisfactory months? Seneral Comment: Review of 2012-2013 capacity reviews conducted by engineering indicate they were reviewed as required and were found to have adequate capacities. 192.603(b)][192.741(a),192.741(b)] Is each distribution system supplied by more than one district pressure regulating station, or where required by the operator on a system supplied by a single regulating station, or where required by the operator on a system supplied by a single regulating station, peruipped with telemetering or recording pressure gauges to indicate the gas pressure in the district? Seneral Comment: Whill fed systems are monitored by pressure recording charts. Staff conducted a random review of pressure recording charts and observed no indications of abnormally pressures in 2012-2013. If there were indications of abnormally high- or low-pressure, were actions taken to correct any unsatisfactory operating conditions? Seneral Comment: Review of random weekly charts for 2012-2013 indicate there were no excessive high or low pressures observed. 192.603(b)][192.743(a),192.743(b),192.195(b)(2)] Is overpressure protection provided by the supplier pipeline downstream of the take point? Yes Seneral Comment: Currently Liberty is in the process of purchasing property at both take points in the Harrisburg system to allow for these stations to be rebuilt and will include overpressure protection as part of the new design. If Yes, does the operator have decumentation to verify that these devices have adequate capacity?	Review of the 2012-2013 inspections for pressure regu conducted within the allowable time frames and were s	ulating and overpressure protection equipment in the Harrisburg system inc et within allowable pressure ranges for the applicable MAOP's.	dicated the inspections were
Review of capacity reviews conducted in 2012-2013 indicate adequate relief capacities are being maintained in the Harrisburg system. 192.603(b)][192.743(b)] If the operator used calculations to determine sufficient capacity, were the calculation reviews documented at a minimum of 1 per year/15 months? Seneral Comment: Review of 2012-2013 capacity reviews conducted by engineering indicate they were reviewed as required and were found to have adequate capacities. 192.603(b)][192.741(a),192.741(b)] Is each distribution system supplied by more than one district pressure regulating station, or where required by the operator on a system supplied by a single regulating station, equipped with telemetering or recording pressure gauges to indicate the gas pressure in the district? Seneral Comment: Multi fed systems are monitored by pressure recording charts. Staff conducted a random review of pressure recording charts and observed no indications of abnormal pressures in 2012-2013. If there were indications of abnormally high- or low-pressure, were actions taken to correct any unsatisfactory operating conditions? Seneral Comment: Review of random weekly charts for 2012-2013 indicate there were no excessive high or low pressures observed. 192.603(b)][192.743(a),192.743(b),192.195(b)(2)] Is overpressure protection provided by the supplier pipeline downstream of the take point? Yes Seneral Comment: Currently Liberty is in the process of purchasing property at both take points in the Harrisburg system to allow for these stations to be rebuilt and will include by verify that these devices have adequate capacity? Satisfactory	[192.603(b)][192.743(a)]	regulating stations for adequate capacity at a	Satisfactory
If the operator used calculations to determine sufficient capacity, were the calculation reviews documented at a minimum of 1 per year/15 months? Seneral Comment: Review of 2012-2013 capacity reviews conducted by engineering indicate they were reviewed as required and were found to have adequate capacities. 192.603(b)][192.741(a),192.741(b)] Is each distribution system supplied by more than one district pressure regulating station, or where required by the operator on a system supplied by a single regulating station, equipped with telemetering or recording pressure gauges to indicate the gas pressure in the district? Seneral Comment: Whiti fed systems are monitored by pressure recording charts. Staff conducted a random review of pressure recording charts and observed no indications of abnormal pressures in 2012-2013. 192.603(b)][192.741(c)] If there were indications of abnormally high- or low-pressure, were actions taken to correct any unsatisfactory operating conditions? Seneral Comment: Review of random weekly charts for 2012-2013 indicate there were no excessive high or low pressures observed. 192.603(b)][192.743(a),192.743(b),192.195(b)(2)] Is overpressure protection provided by the supplier pipeline downstream of the take point? Seneral Comment: Currently Liberty is in the process of purchasing property at both take points in the Harrisburg system to allow for these stations to be rebuilt and will include overpressure protection as part of the new design. If Yes, does the operator have documentation to verify that these devices have adequate capacity?	General Comment:		
sufficient capacity, were the calculation reviews documented at a minimum of 1 per year/15 months? Seneral Comment: Review of 2012-2013 capacity reviews conducted by engineering indicate they were reviewed as required and were found to have adequate capacities. 192.603(b)][192.741(a),192.741(b)] Is each distribution system supplied by more than one district pressure regulating station, or where required by the operator on a system supplied by a single regulating station, equipped with telemetering or recording pressure gauges to indicate the gas pressure in the district? Seneral Comment: Wulli fed systems are monitored by pressure recording charts. Staff conducted a random review of pressure recording charts and observed no indications of abnormal pressures in 2012-2013. If there were indications of abnormally high- or low-pressure, were actions taken to correct any unsatisfactory operating conditions? General Comment: Review of random weekly charts for 2012-2013 indicate there were no excessive high or low pressures observed. 192.603(b)][192.743(a),192.743(b),192.195(b)(2)] Is overpressure protection provided by the supplier pipeline downstream of the take point? Yes General Comment: Currently Liberty is in the process of purchasing property at both take points in the Harrisburg system to allow for these stations to be rebuilt and will include by everpressure protection as part of the new design. If Yes, does the operator have documentation to verify that these devices have adequate capacity?	Review of capacity reviews conducted in 2012-2013 in	dicate adequate relief capacities are being maintained in the Harrisburg sy	rstem.
Review of 2012-2013 capacity reviews conducted by engineering indicate they were reviewed as required and were found to have adequate capacities. Is each distribution system supplied by more than one district pressure regulating station, or where required by the operator on a system supplied by a single regulating station, equipped with telemetering or recording pressure gauges to indicate the gas pressure in the district? Staff conducted a random review of pressure recording charts and observed no indications of abnormal pressures in 2012-2013. If there were indications of abnormally high- or low-pressure, were actions taken to correct any unsatisfactory operating conditions? General Comment: Review of random weekly charts for 2012-2013 indicate there were no excessive high or low pressures observed. Is overpressure protection provided by the supplier pipeline downstream of the take point? Yes General Comment: Currently Liberty is in the process of purchasing property at both take points in the Harrisburg system to allow for these stations to be rebuilt and will include overpressure protection as part of the new design. If Yes, does the operator have documentation to verify that these devices have adequate capacity?	[192.603(b)][192.743(b)]	sufficient capacity, were the calculation reviews documented at a minimum of 1 per year/15	Satisfactory
Is each distribution system supplied by more than one district pressure regulating station, or where required by the operator on a system supplied by a single regulating station, equipped with telemetering or recording pressure gauges to indicate the gas pressure in the district? **Satisfactory** **Pes** **Satisfactory** **Satisfactory** **Jes** **Satisfactory** **Jes** **Satisfactory** **Satisfactory** **Jes**	General Comment:	·	
one district pressure regulating station, or where required by the operator on a system supplied by a single regulating station, equipped with telemetering or recording pressure gauges to indicate the gas pressure in the district? **Multi fed systems are monitored by pressure recording charts.** **Staff conducted a random review of pressure recording charts and observed no indications of abnormal pressures in 2012-2013.** **If there were indications of abnormally high- or low-pressure, were actions taken to correct any unsatisfactory operating conditions?* **Seneral Comment:** **Review of random weekly charts for 2012-2013 indicate there were no excessive high or low pressures observed.** **Ing. 603(b)][192.743(a),192.743(b),192.195(b)(2)] Is overpressure protection provided by the supplier pipeline downstream of the take point?* **Seneral Comment:** **Currently Liberty is in the process of purchasing property at both take points in the Harrisburg system to allow for these stations to be rebuilt and will include overpressure protection as part of the new design.** **If Yes, does the operator have documentation to verify that these devices have adequate capacity?** **Satisfactory*	Review of 2012-2013 capacity reviews conducted by ea	ngineering indicate they were reviewed as required and were found to hav	e adequate capacities.
General Comment: Multi fed systems are monitored by pressure recording charts. Staff conducted a random review of pressure recording charts and observed no indications of abnormal pressures in 2012-2013. If there were indications of abnormally high- or low-pressure, were actions taken to correct any unsatisfactory operating conditions? General Comment: Review of random weekly charts for 2012-2013 indicate there were no excessive high or low pressures observed. In 20.603(b) [192.743(a),192.743(b),192.195(b)(2)] Is overpressure protection provided by the supplier pipeline downstream of the take point? General Comment: Currently Liberty is in the process of purchasing property at both take points in the Harrisburg system to allow for these stations to be rebuilt and will include overpressure protection as part of the new design. If Yes, does the operator have documentation to verify that these devices have adequate capacity? Satisfactory	[192.603(b)][192.741(a),192.741(b)]	one district pressure regulating station, or where required by the operator on a system supplied by a single regulating station, equipped with telemetering or recording pressure gauges to	Satisfactory
If there were indications of abnormally high- or low-pressure, were actions taken to correct any unsatisfactory operating conditions? General Comment: Review of random weekly charts for 2012-2013 indicate there were no excessive high or low pressures observed. [192.603(b)][192.743(a),192.743(b),192.195(b)(2)] Is overpressure protection provided by the supplier pipeline downstream of the take point? General Comment: Currently Liberty is in the process of purchasing property at both take points in the Harrisburg system to allow for these stations to be rebuilt and will include overpressure protection as part of the new design. [192.603(b)][192.743(a)] If Yes, does the operator have documentation to verify that these devices have adequate capacity?	General Comment:		
low-pressure, were actions taken to correct any unsatisfactory operating conditions? General Comment: Review of random weekly charts for 2012-2013 indicate there were no excessive high or low pressures observed. [192.603(b)][192.743(a),192.743(b),192.195(b)(2)] Is overpressure protection provided by the supplier pipeline downstream of the take point? General Comment: Currently Liberty is in the process of purchasing property at both take points in the Harrisburg system to allow for these stations to be rebuilt and will include overpressure protection as part of the new design. [192.603(b)][192.743(a)] If Yes, does the operator have documentation to verify that these devices have adequate capacity?	Multi fed systems are monitored by pressure recording abnormal pressures in 2012-2013.	charts. Staff conducted a random review of pressure recording charts and	d observed no indications of
Review of random weekly charts for 2012-2013 indicate there were no excessive high or low pressures observed. [192.603(b)][192.743(a),192.743(b),192.195(b)(2)] Is overpressure protection provided by the supplier pipeline downstream of the take point? [201.603(b)][192.743(a)] Is overpressure protection provided by the supplier pipeline downstream of the take point? [201.603(b)][192.743(a)] If Yes, does the operator have documentation to verify that these devices have adequate capacity?	[192.603(b)][192.741(c)]	low-pressure, were actions taken to correct any	Satisfactory
[192.603(b)][192.743(a),192.743(b),192.195(b)(2)] Is overpressure protection provided by the supplier pipeline downstream of the take point? [202.603(b)][192.743(a),192.743(b),192.195(b)(2)] Is overpressure protection provided by the supplier pipeline downstream of the take point? [202.603(b)][192.743(a)] Is overpressure protection provided by the supplier pipeline downstream of the take point? [202.603(b)][192.743(a)] Is overpressure protection provided by the supplier pipeline downstream of the take point? [202.603(b)][192.743(a)] Is overpressure protection provided by the supplier pipeline downstream of the take point? [202.603(b)][192.743(a)] Is overpressure protection provided by the supplier pipeline downstream of the take point? [202.603(b)][192.743(a)] Is overpressure protection provided by the supplier pipeline downstream of the take point? [202.603(b)][192.743(a)] Is overpressure protection provided by the supplier pipeline downstream of the take point? [202.603(b)][192.743(a)] Is overpressure protection provided by the supplier pipeline downstream of the take point? [202.603(b)][192.743(a)] Is overpressure protection provided by the supplier pipeline downstream of the take point? [202.603(b)][192.743(a)] Is overpressure protection provided by the supplier pipeline downstream of the take point? [202.603(b)][192.743(a)] Is overpressure protection provided by the supplier pipeline downstream of the take point? [202.603(b)][192.743(a)] Is overpressure protection provided by the supplier pipeline downstream of the take point?	General Comment:	<u>.</u>	
Supplier pipeline downstream of the take point? General Comment: Currently Liberty is in the process of purchasing property at both take points in the Harrisburg system to allow for these stations to be rebuilt and will include overpressure protection as part of the new design. If Yes, does the operator have documentation to verify that these devices have adequate capacity? Satisfactory	Review of random weekly charts for 2012-2013 indicate	e there were no excessive high or low pressures observed.	
Currently Liberty is in the process of purchasing property at both take points in the Harrisburg system to allow for these stations to be rebuilt and will include overpressure protection as part of the new design. If Yes, does the operator have documentation to verify that these devices have adequate capacity? Satisfactory	[192.603(b)][192.743(a),192.743(b),192.195		Yes
If Yes, does the operator have documentation to verify that these devices have adequate capacity? Satisfactory	General Comment:	· · ·	
verify that these devices have adequate capacity?	Currently Liberty is in the process of purchasing proper overpressure protection as part of the new design.	rty at both take points in the Harrisburg system to allow for these stations to	o be rebuilt and will include
General Comment:	[192.603(b)][192.743(a)]		Satisfactory
	General Comment:	· · · · · · · · · · · · · · · · · · ·	

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

VAI	VE MAINTENANCE	Status
[192.603(b)][192.747(a),192.747(b)]	Did the operator inspect and maintain distribution valves necessary for the safe operation of the system at a minimum of 1 per year/15 months?	Satisfactory
General Comment:	·	
Review of the valve inspections performed in 2012 the valve inspections reviewed were completed as	-2013 were conducted within the allowable intervals. Random review of complete required by company procedures.	ted valve inspections indica
192.603(b)][192.749(a)]	Did the operator inspect and maintain vaults > 200 cubic feet at a minimum of 1 per year/15 months?	Not Applicable
General Comment:	<u> </u>	
There are no vaults in the Harrisburg system meet	ing these requirements.	
Inve	stigation Of Failures	Status
[192.603(b)][192.617]	Did the operator experience accidents or failures requiring analysis?	Not Applicable
General Comment:		
There were no failures or accidents in 2012-2013 t	hat required analysis.	
	hat required analysis. DING OF STEEL PIPE	Status
WEL		Status Satisfactory
WEL [192.603(b)][192.225(b)]	DING OF STEEL PIPE Does the operator have documentation for their	
[192.603(b)][192.225(b)] General Comment:	DING OF STEEL PIPE Does the operator have documentation for their	
WEL [192.603(b)][192.225(b)] General Comment: Review of the welding procedures located in the Li	DING OF STEEL PIPE Does the operator have documentation for their qualified welding procedure?	
WEL [192.603(b)][192.225(b)] General Comment: Review of the welding procedures located in the Life [192.603(b)][192.227,192.229]	Ding of Steel Pipe Does the operator have documentation for their qualified welding procedure? berty Welding Manual determined they have qualified welding procedures. Does the operator have documentation of welder	Satisfactory
WEL [192.603(b)][192.225(b)] General Comment: Review of the welding procedures located in the Li [192.603(b)][192.227,192.229] General Comment:	Ding of Steel Pipe Does the operator have documentation for their qualified welding procedure? berty Welding Manual determined they have qualified welding procedures. Does the operator have documentation of welder	Satisfactory
WEL [192.603(b)][192.225(b)] General Comment: Review of the welding procedures located in the Life [192.603(b)][192.227,192.229] General Comment:	Ding of Steel Pipe Does the operator have documentation for their qualified welding procedure? berty Welding Manual determined they have qualified welding procedures. Does the operator have documentation of welder qualification as required?	Satisfactory
WEL 192.603(b)][192.225(b)] General Comment: Review of the welding procedures located in the Li 192.603(b)][192.227,192.229] General Comment: Review of 2012-2013 welder qualifications indicate	Ding of Steel Pipe Does the operator have documentation for their qualified welding procedure? berty Welding Manual determined they have qualified welding procedures. Does the operator have documentation of welder qualification as required? It is they were re-qualified per API-1104 requirements. Does the operator have documentation of welder	Satisfactory Satisfactory
WEL 192.603(b)][192.225(b)] General Comment: Review of the welding procedures located in the Li 192.603(b)][192.227,192.229] General Comment: Review of 2012-2013 welder qualifications indicate 192.807]	Ding of Steel Pipe Does the operator have documentation for their qualified welding procedure? berty Welding Manual determined they have qualified welding procedures. Does the operator have documentation of welder qualification as required? In they were re-qualified per API-1104 requirements. Does the operator have documentation of welder OQ records?	Satisfactory Satisfactory

No NDT was conducted in 2012-1013.

[192.709][192.243(f)]	Does the operator have documentation of NDT testing performed?	Not Applicable
General Comment:		
No NDT was conducted in 2012-1013.		
JOINING OF MAT	TERIAL OTHER THAN WELDING	Status
[192.603(b)][192.285]	Are persons making joints with plastic pipe qualified?	Satisfactory
General Comment:		
Review of individuals qualified for plastic fusion indi	cates they were re-qualified as required in 2012-2013.	
[192.603(b)][192.287]	Are persons inspecting plastic pipe joints qualified?	Satisfactory
General Comment:		
Review of individuals qualified for plastic fusion indi	icates they were re-qualified as required in 2012-2013.	
[192.603(b)][192.283]	Are qualified joining procedures for plastic pipe in place?	Satisfactory
General Comment:		
	Construction Manual which is part of the O&M indicate they are qualified as re	equired. These are PPI
Review of Liberty's fusion procedures located in the procedures that were adopted by Liberty.	Construction Manual which is part of the O&M indicate they are qualified as re ON CONTROL RECORDS	equired. These are PPI Status
Review of Liberty's fusion procedures located in the procedures that were adopted by Liberty.		·
Review of Liberty's fusion procedures located in the procedures that were adopted by Liberty. CORROSI	ON CONTROL RECORDS Has the operator maintained maps or records of cathodically protected piping, cathodic protection facilities, galvanic anodes, and neighboring structures bonded to the cathodic protection	Status
Review of Liberty's fusion procedures located in the procedures that were adopted by Liberty. CORROSI: [192.491(a)][192.491(a)] General Comment: Liberty currently maintains paper maps of cathodical	ON CONTROL RECORDS Has the operator maintained maps or records of cathodically protected piping, cathodic protection facilities, galvanic anodes, and neighboring structures bonded to the cathodic protection	Status Satisfactory
Review of Liberty's fusion procedures located in the procedures that were adopted by Liberty. CORROSI: [192.491(a)][192.491(a)] General Comment: Liberty currently maintains paper maps of cathodical	ON CONTROL RECORDS Has the operator maintained maps or records of cathodically protected piping, cathodic protection facilities, galvanic anodes, and neighboring structures bonded to the cathodic protection system?	Status Satisfactory
Review of Liberty's fusion procedures located in the procedures that were adopted by Liberty. CORROSI: [192.491(a)][192.491(a)] General Comment: Liberty currently maintains paper maps of cathodical Wennsoft program. Folders are maintained for each	ON CONTROL RECORDS Has the operator maintained maps or records of cathodically protected piping, cathodic protection facilities, galvanic anodes, and neighboring structures bonded to the cathodic protection system? Ally protected piping, anode installations and rectifier locations. Test point reading the system indicating the work that has been performed on that system. Has the operator maintained documentation of an	Status Satisfactory ings are maintained in their
Review of Liberty's fusion procedures located in the procedures that were adopted by Liberty. CORROSI [192.491(a)][192.491(a)] General Comment: Liberty currently maintains paper maps of cathodical Wennsoft program. Folders are maintained for each [192.491][192.459] General Comment:	ON CONTROL RECORDS Has the operator maintained maps or records of cathodically protected piping, cathodic protection facilities, galvanic anodes, and neighboring structures bonded to the cathodic protection system? Ally protected piping, anode installations and rectifier locations. Test point reading the system indicating the work that has been performed on that system. Has the operator maintained documentation of an	Status Satisfactory ings are maintained in their
Review of Liberty's fusion procedures located in the procedures that were adopted by Liberty. CORROSI [192.491(a)][192.491(a)] General Comment: Liberty currently maintains paper maps of cathodical Wennsoft program. Folders are maintained for each [192.491][192.459] General Comment:	Has the operator maintained maps or records of cathodically protected piping, cathodic protection facilities, galvanic anodes, and neighboring structures bonded to the cathodic protection system? Ally protected piping, anode installations and rectifier locations. Test point reading the system indicating the work that has been performed on that system. Has the operator maintained documentation of an examination when buried pipe was exposed?	Status Satisfactory ings are maintained in their
Review of Liberty's fusion procedures located in the procedures that were adopted by Liberty. CORROSI: [192.491(a)][192.491(a)] General Comment: Liberty currently maintains paper maps of cathodical Wennsoft program. Folders are maintained for each [192.491][192.459] General Comment: Review of SSD orders completed in 2012-2013 indicates the procedure of th	Has the operator maintained maps or records of cathodically protected piping, cathodic protection facilities, galvanic anodes, and neighboring structures bonded to the cathodic protection system? Ally protected piping, anode installations and rectifier locations. Test point reading the system indicating the work that has been performed on that system. Has the operator maintained documentation of an examination when buried pipe was exposed? Has the operator maintained documentation of annual pipe-to-soil monitoring performed at a minimum of 1 per yr/15 months and/or isolated services or short sections of main less than 100	Status Satisfactory ings are maintained in their Satisfactory

they were inspected in 2012-2013 as required and	were conducted on a five year interval.	
[192.491][192.465(b)]	Has the operator maintained documentation of rectifier or other impressed current power sources inspections at a minimum of 6 per year/ 2 1/2 months?	Satisfactory
General Comment:		
Review of rectifier inspections determined they we	re inspected 6 times a year in 2012-2013.	
[192.491][192.465(c)]	Has the operator maintained documentation of each critical interference bond, reverse current switch, diode, etc. inspections at a minimum of 6 per year/ 2 1/2 months and/or non-critical interference bond inspections at a minimum of 1 per year/15 months?	Not Applicable
General Comment:		
There are no critical or non-critical bonds in the Ha	rrisburg Service area.	
[192.491][192.465(d)]	Has the operator taken prompt remedial actions to correct any deficiencies indicated by the monitoring?	Satisfactory
General Comment:		
Review of Breaches issued due to deficiencies obstoremediate the deficiency.	erved during corrosion monitoring inspections performed in 2012-2013, indica	te corrective actions were taken
[192.491][192.465(e)]	Has the operator maintained documentation of unprotected pipeline surveys, inspections, or tests at a minimum of 3 years/39 months?	Satisfactory
General Comment:		
Review of leak surveys conducted on unprotected during the leak surveys, hot spotting was initiated by	piping indicate the surveys were conducted on a three year cycle in 2012-2013 by adding anodes during the leak repair.	3. In areas of corrosion identified
[192.491][192.467(a),192.467(c),192.467	Has the operator maintained documentation of inspections or tests for electrical isolation at casings?	Satisfactory
General Comment:		
Review of casing test points indicate they were ins	pected as required in 2012-2013.	
[192.491][192.469]	Does the operator have a sufficient number of test stations or other contact points for electrical measurement to determine the adequacy of cathodic protection?	Satisfactory
General Comment:		
Liberty determines the number of test points according the start and end of the system.	ding to the size of the system. Test points are then spotted throughout the sys	tem with a minimum of one at
	Has the operator maintained documentation of	

	corrective actions taken when a test lead is no longer electrically conductive?	
General Comment:	,	
No issues with test leads were identified in 2012-2013.		
[192.491][192.473(b)]	Has the operator maintained documentation of inspections or tests to assure their cathodic protection system is not affecting adjacent underground metallic structures?	Not Applicable
General Comment:		
No rectifiers were installed in the Harrisburg system 20 structures or utilities.	12-2013. If a rectifier is installed, Liberty conducts testing to determine if	they are affecting neighboring
[192.491][192.475(a)]	Has the operator maintained documentation of investigations or steps taken to minimize internal corrosion due to transportation of corrosive gas?	Not Applicable
General Comment:		
Liberty is not transporting corrosive gas in the Harrisbur	rg System.	
[192.491][192.475(b)]	Has the operator maintained documentation of internal surface inspections performed when pipe is removed for any reason?	Satisfactory
General Comment:		
Review of 2012-2013 SSD's indicates internal piping in:	spections were conducted when piping was removed.	
[192.491][192.477]	Has the operator maintained documentation of internal corrosion coupon monitoring at a minimum of 2 per year/ 7 1/2 months?	Not Applicable
General Comment:		
There is no internal corrosion coupon monitoring testing	g performed in the Harrisburg system due to no indications of internal con	rosion being identified.
[192.491][192.481]	Has the operator maintained documentation of atmospheric corrosion control monitoring at a minimum of 1 per 3 years/ 39 months?	Satisfactory
General Comment:		
The atmospheric corrosion survey was conducted by Li	berty in 2012 with the previous surveys being conducted in 2009 and 201	11.
[192.491][192.479]	Has the operator maintained documentation of corrective action where atmospheric corrosion was discovered?	Satisfactory
General Comment:		
Review of the atmospheric corrosion survey conducted of corrosion were identified.	in the Harrisburg Service Area in 2012 indicated that corrective actions w	vere completed where indications
[192.491][192.483(a),192.483(b),192.483(c)]	Has the operator maintained documentation	Satisfactory

	corrosion has been repaired or replaced with pipe that was coated and cathodically protected?	
General Comment: Review of corrective actions due to the fi	indings of the atmospheric corrosion survey, indicated piping was removed when wall loss	was identified. A majority of
	r where coating failures had occurred. One riser was repaired using Trident pipe repair m	
TR	AINING - 83 IL ADM. CODE 520	Status
[520.10(a) (1)]	Has the operator maintained documentation demonstrating that personnel have received adequate training?	Satisfactory
General Comment:		
Review of current employee qualification	s indicate documentation is being maintained to demonstrate that personnel have received	d the required training.
[520.10(a) (2)]	Do training records include verbal instruction and/or on the job training for each job classification?	Satisfactory
General Comment:	<u> </u>	
The operator maintains documentation o	f training and meetings held with operating personnel and indicates what training is provid	led.
[520.10(b)]	Has the municipal operator maintained documentation demonstrating that personnel have received adequate training?	Not Applicable
General Comment:	<u> </u>	
Liberty is not a municipal operator.		
[520.10(a)(5)]	Are procedures periodically updated to include new materials, new methods of operation and installation, and changes in general procedures?	Satisfactory
General Comment:	<u> </u>	
There was no new products or methods in	initiated in 2012-2013 that would have required training or qualification.	